





---

# Broadway Ave Pipe Replacement

Village Manager Sarkozy

# Location of Pipe

- Broadway Avenue, West of Poinciana Avenue



# Condition of Pipe

- The section of aluminum pipe, which goes below Broadway Avenue, will be replaced with a concrete pipe





# Road Deterioration

---

- The breakdown of the pipe has led to a deterioration in road condition above the pipe



# Project Outline

---

- Replace current metal pipe with concrete pipe, which will have longer useful life
- Increase flow capacity by installing larger pipe lines
- Repair damaged road and noticeable bump at pipe crossing
- Minor improvements to drainage structure to reduce risk to passing vehicles

# Questions?

---

